CORRES CONTROL **INCOMING LTR NO** 

00358 RF 01

DUE DATE ACTION

2001 HAY 24 P 1 34 Department of Energy CORRESPONDENCE CONTROL **ROCKY FLATS FIELD OFFICE** 

10606 HIGHWAY 93, UNIT A GOLDEN COLORADO 80403-8200

MAY 2 3 2001

01 DOE-00848

DIST	TR	ENC
BOGENBERGER, V.		
BRAILSFORD, M.D.		1-7
BURNS, T.F.	$\vdash$	<del>                                     </del>
CIAGLO, T.	V	
DECK, C.A. DIETERLE, S.E.	<u> </u>	1—−
FERRERA. D.W.	1	<del>                                     </del>
FERRI, M.S.		
FRASER, R.G. FULTON, J.C.	┼	├
GERMAIN, A.L.	1	
GIACOMINI. J.		
LEONARD, R.C.	—	}
MARTINEZ LA	1-	
MOTES, J.L.		
NORTH, K. PARKER, A.M.	<del> </del>	<u> </u>
POWERS, K.P.	<del> </del>	┢
RAAZ R.D.		
RODGERS, A.D. SANDLIN, N.B.	٠.	<b></b> -
SANDLIN, N.B.	<u> </u>	<b></b>
SHELTON, D.C.		
SPEARS, M.	<b> </b> -	├
TRICE, K.D.	<del>                                     </del>	
VOORHEIS, G.M.		
Drives A		
Augustick	۲.,	<b>—</b>
PHU De		
Homes, A	$\vdash 4$	_
	$\vdash \vdash$	

Mr Timothy Rehder Rocky Flats Team Lead U.S. Environmental Protection Agency Region VIII 999 18th Street Suite 500 EPR FT Denver Colorado 80202 2450

In accordance with the Rocky Flats Cleanup Agreement (RFCA) requirement in Attachment 5 Subpart 2 4(B) Actions Determinations we are providing two copies of the enclosed Source Evaluation Report for RFCA Point of Evaluation (POE) SW027 Specifically this report addresses the September 12 2000 notification of reportable 30 day moving averages for plutonium (Pu) water-quality results in the South Interceptor Ditch (SID) The associated reportable values were measured at the RFCA POE SW027 monitoring location on the SID just upstream of Pond C 2 for the periods June 26 29 2000 July 18 21 2000; and August 18 20 2000 This Source Evaluation Report fulfills the commitment outlined in our notification letter to you dated September 6 2000

Briefly the enclosed report identifies only diffuse radionuclide contamination from past Rocky Flats Environmental Technology Site operations as the possible cause of these reportable values No specific recommendations for source control are proposed in response to these measured values Our proposed course of action includes 1) continued monitoring. 2) integration of these results to support progress on the Actinide Migration Evaluation and

3) stormwater control

If you have any questions concerning this report please contact me at (303) 966-5918 or Glenn Doyle at (303) 966 3087

Sincerely

Assistant Manager

for Environment and Infrastructure

COR. CONTROL ADMN. RECORD

Reviewed for Addressee Corres Control RFP

Ref Ltr #

Enclosure (2 copies)

DOE ORDER #

Mr Timothy Rehder 01 DOE-00/848

2

MAY 2 3 2001

cc w/o Enc G Doyle AMEI RFFO J Stover AI RFFO D Shelton K H R Nininger K H

cc w/Enc
R DiSalvo OCC RFFO
L Brooks K H
CERCLA Administrative Record

1/2